#### HISTORIC AMERICAN BUILDINGS SURVEY

#### INDEX TO PHOTOGRAPHS

SAN QUENTIN STATE PRISON, BUILDING 22

HABS CA-2804-A

Point San Quentin San Quentin Marin California

#### INDEX TO BLACK AND WHITE PHOTOGRAPHS

### Robert A Hicks, photographer, September 2007

CA-2804-A-I	Contextual view of Building 22, north and east façades; southwesterly view
CA-2804-A-2	Contextual view of Building 22, north and west façades; southeasterly view
CA-2804-A-3	Contextual view of Building 22, west façade; easterly view
CA-2804-A-4	Contextual view of Building 22, west façade; northeasterly view
CA-2804-A-5	Contextual view of Building 22, south and west façades; northwesterly view
CA-2804-A-6	Contextual view of Building 22, east façade; westerly view
CA-2804-A-7	Contextual view of Building 22, east façade; southwesterly view
CA-2804-A-8	Contextual view of Building 22, north and east façades; southwesterly view
CA-2804-A-9	Contextual view of Building 22, north and west façades; southeasterly view
CA-2804-A-I0	Contextual view of Building 22, west façade; southeasterly view
CA-2804-A-II	Exterior building details of Building A; elevation of east façade; westerly view

CA-2804-A-12	Exterior building details of Building A; oblique east façade; southwesterly view
CA-2804-A-13	Exterior building details of Building A; elevation of north façade; southerly view
CA-2804-A-14	Exterior building details of Building A; oblique east façade; southeasterly view
CA-2804-A-15	Exterior building details of Building A; elevation of west façade; easterly view
CA-2804-A-16	Exterior building details of Building A; east façade: concrete staircase, profiled cement, plaster door surround, recessed panel inscribed "1859", historic window opening with concrete sill above door, cement plaster dentil course and cornice truncated wood beam ends, plaster finished brick wall, granite base; westerly view
CA-2804-A-17	Exterior building details of Building A; east façade: profiled cement plaster door surround, black mesh gate protects a two-light transom atop non-original metal door; westerly view
CA-2804-A-18	Exterior building details of Building A; east façade: fixed five- over-five wood windows with five-light hoppers with concrete sills; westerly view
CA-2804-A-19	Exterior building details of Building A; east façade: recessed panel inscribed "1859", historic window opening with concrete sill above door, cement plaster dentil course and cornice, truncated wood beam ends, plaster finished brick wall, granite base; westerly view
CA-2804-A-20	Exterior building details of Building A; north façade: iron latticed gate dungeon entrance, granite base; southerly view
CA-2804-A-21	Exterior building details of Building A; north façade: four-over-four double-hung wood sash window with concrete sill; southerly view
CA-2804-A-22	Exterior building details of Building A; north façade: two three-light wood casement windows flank a three-light fixed wood window with concrete sill; southerly view

CA-2804-A-23	Exterior building details of Building A; west façade: exposed common bond brick wall, arched brick lintels over a two single-light casement window with brick sills, arched brick lintel over door cornice; easterly view
CA-2804-A-24	Exterior building details of Building A; west façade: white painted brick wall of road and second level, road level: paired four-light casement window and a small single-light wood casement window; second level: four-over-four wood double-hung window and a six-light horizontal pivot over a three-light fixed window; easterly view
CA-2804-A-25	Interior building details of Building A, dungeon central hallway: poured concrete floors, plaster-finished brick walls, vaulted ceiling, arch entryway to cells; southerly view
CA-2804-A-26	Interior building details of Building A, dungeon northwest cell: poured concrete floors, plastered finished walls, exposed brick wall, vaulted veiling; westerly view
CA-2804-A-27	Interior building details of Building A, dungeon cell adjacent to northwest cell: granite and brick threshold, poured concrete floors, plastered finished walls, vaulted veiling; northwesterly view
CA-2804-A-28	Interior building details of Building A, Room A-001: plastered painted west brick wall, mezzanine structure, wood ceiling; southerly view
CA-2804-A-29	Interior building details of Building A, Room A-002: plastered painted west brick wall, four light double-hung wood window with brick arch lintel, east plastered wall (could be granite), wood ceiling; northerly view
CA-2804-A-30	Interior building details of Building A, Room A-101: painted wood staircase, wood handrails with metal brackets, plastered finished brick walls; westerly view
CA-2804-A-31	Interior building details of Building A, Room A109 Dutch door, room A-108 single panel wood door with wood trim northerly view

CA-2804-A-32	Interior building details of Building A, Room A-102 plastered finished brick wall, Room A-103 plaster finished partition walls; northeasterly view
CA-2804-A-33	Interior building details of Building A, Room 2-212: plaster ceiling and one-over-one double hung wood sash over a fixed three-light window, Room A-213 painted plaster finished partition walls; easterly view
CA-2804-A-34	Interior building details of Building A, Room 2-212: plaster ceiling and two-over-two double-hung wood sash with a infilled panel below, window, Room A-213 painted plaster finished partition walls; easterly view
CA-2804-A-35	Exterior building details of Building B, oblique east façade; northwesterly view
CA-2804-A-36	Exterior building details of Building B, elevation of east façade; westerly view
CA-2804-A-37	Exterior building details of Building B, oblique of east façade; southwesterly view
CA-2804-A-38	Exterior building details of Building B, elevation of west façade; easterly view
CA-2804-A-39	Exterior building details of Building B, oblique west façade; northwesterly view
CA-2804-A-40	Exterior building details of Building B, east façade: ell-shaped south facing concrete staircase with decorative pipe railing, second floor entrance with cement plaster profiled surround, dentil course cornice, truncated embedded wood beams, cream colored plaster-finished exterior façade, closed off window well with protruding vent; northwesterly view
CA-2804-A-41	Exterior building details of Building B, east façade: second floor entrance with cement plaster profiled surround and embedded wood beam end; westerly view

CA-2804-A-42	Exterior building details of Building B, east façade: embedded wood beams and interrupted dentil course cornice resulting from the removal of the third floor tuberculosis ward, yard level paneled Dutch door, second level two a typical six-light wood casement windows over a single-panel wood door with four light exits to fire escape; westerly view
CA-2804-A-43	Exterior building details of Building B, east façade: ca. 1914 covered porch with an asphalt singled low-hipped roof; southwesterly view
CA-2804-A-44	Exterior building details of Building B, west façade: brick infilled historic arched opening with window, square vent and gated door entry; easterly view
CA-2804-A-45	Exterior building details of Building B, west façade: two painted-wood single-light casements over two-light casements with concrete sill and arch brick lintel, over infilled brick patch with arch brick lintel, brick lintel above windows and brick infilled oval; easterly view
CA-2804-A-46	Exterior building details of Building B, west façade: road level four-over-four double-hung painted-wood windows with brick sill and arch brick lintels; easterly view
CA-2804-A-47	Interior building details of Building B, Room B-004: north, west, and south brick wall and wood beams, westerly view
CA-2804-A-48	Interior building details of Building B, Room B-004: south brick wall partial painted brick plaster with stair scar trace, historic brick infilled arch entry way to Room C-001; southeasterly view
CA-2804-A-49	Interior building details of Building B, Room B-003: wood columns and kickers; southeasterly
CA-2804-A-50	Interior building details of Building B, Room B-003: enact eight light window over four window light door, six window over double three light window and painted west brick wall; westerly view

CA-2804-A-51	Interior building details of Building B, Room B-001: single panel door to Room B-001e and plaster painted brick wall; southeasterly view
CA-2804-A-52	Interior building details of Building B, Room B-001: north painted north brick wall, two-panel wood bathroom door; northeasterly view
CA-2804-A-53	Interior building details of Building B, Room B-001b, wood T staircase, Room B-001c, painted plaster north brick wall; northerly view
CA-2804-A-54	Interior building details of Building B, Room B-001: four-over-four wood painted wood with brick sill and painted plaster west brick wall; westerly view
CA-2804-A-55	Interior building details of Building B, Room B-002m northerly light well under road level and circular stair trace behind circular wood shelving; easterly view
CA-2804-A-56	Interior building details of Building B, middle light well vertical view up light well to vent at road level; easterly view
CA-2804-A-57	Interior building details of Building B, Room B-103: painted north and south brick wall, tiebacks on south wall; westerly view
CA-2804-A-58	Interior building details of Building B, Room B-101: wood columns and kickers, plywood baton partition wall, painted plaster west brick wall, four-over-four double-hung wood window; westerly view
CA-2804-A-59	Interior building details of Building B, Room B-101: east brick retaining wall, wood ceiling, plywood baton partition wall; easterly view
CA-2804-A-60	Interior building details of Building B, Room B-102: east brick retaining wall, wood ceiling and joist, southeasterly view
CA-2804-A-61	Interior building details of Building B, Room B-102b: wood staircase, painted north brick wall; northeasterly view

CA-2804-A-62	Interior building details of Building B, Room B-203: painted east and south brick walls, tiebacks on south wall; southeasterly view
CA-2804-A-63	Interior building details of Building B, Room B-201 interior space; northwesterly view
CA-2804-A-64	Interior building details of Building B, Room B-201 interior space; southerly view
CA-2804-A-65	Interior building details of Building B, Room B-215: six-light wood casement windows over a single-pane wood door with four light exits to fire escape; easterly view
CA-2804-A-66	Exterior building details of Building C, elevation of east façade; westerly view
CA-2804-A-67	Exterior building details of Building C, oblique east façade; southwesterly view
CA-2804-A-68	Exterior building details of Building C, elevation of west façade; easterly view
CA-2804-A-69	Exterior building details of Building C, oblique south and west façades; northeasterly view
CA-2804-A-70	Exterior building details of Building C, east façade: historic six light entry double door with three light transom, historic six light door with a one light transom, arch brick lintels and quoins, scored cement plaster finished brick walls; westerly view
CA-2804-A-71	Exterior building details of Building C, east façade: inscribed date panel "hospital 1885", corbelled brick belt course, parapet, second floor historic four-over-four window with brick lintels, quoins and decorative metal grilled, cantilever wooden walkway; westerly view
CA-2804-A-72	Exterior building details of Building C, east façade: brick quoins, brick lintels, brick window sills, decorative metal grilles, scored cement finished brick wall; westerly view

	<del>- ••</del>
CA-2804-A-73	Exterior building details of Building C, east façade: historic four-over-four window, brick lintel, brick quoins, corbelled brick cornice, spiral metal staircase to inclined stairs rising to second floor cantilever wooden walkway; westerly view
CA-2804-A-74	Exterior building details of Building C, east façade: rolling metal gate and fence, spiral and inclined staircases; southwesterly view
CA-2804-A-75	Exterior building details of Building C, east façade: detail of spiral metal staircase; southerly view
CA-2804-A-76	Exterior building details of Building C, west façade: arch brick lintel and five light transom; easterly view
CA-2804-A-77	Exterior building details of Building C, west façade: second floor: four-over-four windows, arch brick lintels, brick sills, decorative metal grilles; easterly view
CA-2804-A-78	Exterior building details of Building C, south façade: second floor" four-over-four windows, arch brick lintels, brick sills, decorative metal grilles and tiebacks; northwesterly view
CA-2804-A-79	Interior building details of Building C, Room C-003 interior space and 1930 retrofit pillars; northerly view
CA-2804-A-80	Interior building details of Building C, Room C-001 interior space and 1930 retrofit pillars; southeasterly view
CA-2804-A-81	Interior building details of Building C, Room C-003 and Room C-002 catwalk above false ceiling, east brick retaining wall, brick north wall, 1930 retrofit pillars, wood floor joints; northeasterly view
CA-2804-A-82	Interior building details of Building C, Room C-003 catwalk above false ceiling, south brick wall, two historical arch brink entryways infilled with brick and wood post and kicker; southeasterly view
CA-2804-A-83	Interior building details of Building C, Room C-103 interior space; northerly view

CA-2804-A-84	Interior building details of Building C, Room C-109: historic single painted wood closet for Room C-109b and two panel painted wood door for Room C-109a; northerly view
CA-2804-A-85	Interior building details of Building C, Room C-111: north and west painted plaster walls; northwesterly view
CA-2804-A-86	Interior building details of Building C, Room C-113: historic painted plaster lath partition wall, painted plaster east wall and four light over two light double-hung window; southerly view
CA-2804-A-87	Interior building details of Building C, Room C-114: historic two panel door; westerly view
CA-2804-A-88	Interior building details of Building C, Room C-101: historic painted wood staircase, wood handrails, metal brackets and batter board; westerly view
CA-2804-A-89	Interior building details of Building C, Room C-101: historic painted wood staircase, wood handrails, metal brackets and batter board, northeasterly view
CA-2804-A-90	Interior building details of Building C, Room C-201 to Room C -208: wood entry trim; southerly view
CA-2804-A-91	Interior building details of Building C, Room C-208: historic wood floor, historic partition track on wood floor, four-over-four windows with decorative metal grilles, iron radiator; southeasterly view
CA-2804-A-92	Interior building details of Building C, Room C-208: historic wood floor, four-over-for windows with decorative metal grilles, four light door with four light transom; easterly view
CA-2804-A-93	Interior building details of Building C, Room C-208: historic four panel door; northerly view
CA-2804-A-94	Interior building details of Building C, Room C-203 to Room C-204: historical partition track with folding doors, east painted wall; easterly view
CA-2804-A-95	Interior building details of Building C, Room C-203: detail decorative radiator and four-over-four windows; southwesterly view

CA-2804-A-96	Exterior building details of Building D, oblique east façade; northwesterly view
CA-2804-A-97	Exterior building details of Building D, elevation of east façade; westerly view
CA-2804-A-98	Exterior building details of Building D, oblique east façade; southwesterly view
CA-2804-A-99	Exterior building details of Building D, oblique north and west façades; southeasterly view
CA-2804-A-100	Exterior building details of Building D, elevation of west façade; easterly view
CA-2804-A-101	Exterior building details of Building D, oblique south and west façades; northeasterly view
CA-2804-A-102	Exterior building details of Building D, elevation of south façade and Building E roof; northerly view
CA-2804-A-103	Exterior building details of Building D, east façade: painted concrete east face façade, main entry has flat cement plaster surround, double door six light over panels, two light transom over double door; westerly view
CA-2804-A-104	Exterior building details of Building D, east façade: metal casement four light windows; westerly view
CA-2804-A-105	Exterior building details of Building D, west façade: brick arch lintel over historic entry that was brick infilled; easterly view
CA-2804-A-106	Exterior building details of Building D, west façade: two-over- two over two glazed transom over non contributed door with a brick arch lintel; easterly view
CA-2804-A-107	Exterior building details of Building D, west façade: double- hung wood window with brick arch lintel and brick sill; easterly view
CA-2804-A-108	Exterior building details of Building D, west façade: exterior plumbing and sewer pipes and brick infilled windows; southeasterly view

CA-2804-A-109	Exterior building details of Building D, west façade: second floor metal multi-pane industrial-type sash windows; easterly view
CA-2804-A-110	Interior building details of Building D, Room D-007 to Room E -001 passageway interior space; southerly view
CA-2804-A-111	Interior building details of Building D, Room D-007b painted plaster east wall; easterly view
CA-2804-A-112	Interior building details of Building D, Room D-007b painted plaster east wall; southeasterly view
CA-2804-A-113	Interior building details of Building D, Room D-007 to Room D -004 interior space; northerly view
CA-2804-A-114	Interior building details of Building D, Room D-004 interior space; southerly view
CA-2804-A-115	Interior building details of Building D, Room D-004 northwest cell, painted plaster wall, tiebacks on north painted plaster wall; easterly view
CA-2804-A-116	Interior building details of Building D, Room D-004 northwest cell, painted plaster wall, tiebacks on north painted plaster wall; easterly view
CA-2804-A-117	Interior building details of Building D, Room D-005: east plastered painted retaining wall and 1930 retrofit pillar; southerly view
CA-2804-A-118	Interior building details of Building D, Room D-001: painted brick west wall; southwesterly view
CA-2804-A-119	Interior building details of Building D, Room D-003: concrete stairs to mezzanine level; northerly view
CA-2804-A-120	Interior building details of Building D, Room D-M5: mezzanine hallway, intact historic asphalt surface flooring, full height partition wall with hoppers and east brick retaining wall with voids from the original veiling joist; southerly view

CA-2804-A-121	Interior building details of Building D, Room D-M2: historic wood trim, full height partition wall with hopper and east brick retaining wall; southeasterly view
CA-2804-A-122	Interior building details of Building D, Room D-M1 interior space; northerly view
CA-2804-A-123	Interior building details of Building D, Room D-M1 interior space with multi pane industrial sash windows; westerly view
CA-2804-A-124	Interior building details of Building D, Room D-M1 detail multi pane industrial sash windows; westerly view
CA-2804-A-125	Interior building details of Building D, Room D-M5: concrete stairs to education room at road level; northerly view
CA-2804-A-126	Interior building details of Building D, Room D-101 interior space with mural on south wall; southerly view
CA-2804-A-127	Interior building details of Building D, Room D-101 partition wall with multi-pane wood sash, timber wood truss ceiling; northerly view
CA-2804-A-128	Interior building details of Building D, Room D-101 to Room D-101c partition wall with multi-pane wood sash; westerly view
CA-2804-A-129	Interior building details of Building D, Room D-101e partition wall with multi-pane wood sash and north wall mural; northerly view
CA-2804-A-130	Interior building details of Building D, Room D-101d interior space with north wall mural; northerly view
CA-2804-A-131	Interior building details of Building D, Room D-101 wood truss detail; northeasterly view
CA-2804-A-132	Exterior building details of Building E, oblique west façade; southeasterly view
CA-2804-A-133	Exterior building details of Building E, elevation of west façade; easterly view
CA-2804-A-134	Exterior building details of Building E, oblique west façade; northeasterly view

CA-2804-A-135	Exterior building details of Building E, oblique west façade: brick arch lintel and parapet; easterly view
CA-2804-A-136	Exterior building details of Building E, oblique west façade: brick arch lintel and brick infilled window with brick sill; southeasterly view
CA-2804-A-137	Interior building details of Building E, Room E-005: interior space and brick partition wall; northeasterly view
CA-2804-A-138	Interior building details of Building E, Room E-001 to D-007 interior space and passage way; northeasterly view
CA-2804-A-139	Interior building details of Building E, Room E-002 to E-002a arch brick plaster wall through the east brick retaining wall; easterly view
CA-2804-A-140	Interior building details of Building E, Room E-002a multi brick arch way under road level all walls and ceiling are brick; northerly view